

Overview

This manual is a guideline to using the two Roland CNC milling machines. This is only a guideline and is not the one-and-only way to setup and run the machines but it is a good way. If you're new to using the machines I would highly recommend doing it this way until you are familiar with both the software and hardware. Once familiar with the setup feel free to make changes to the procedure to better fit your exact needs.

Safety

You must ALWAYS WEAR YOUR SAFETY GLASSES while around the CNC mills. Even if the spindle is not running a carbide tool that breaks due to a collision with the vise or table is just as dangerous as chips off a running cutter.


If you are going to be around the mills an extended amount of time while they are running then you might want to consider hearing protection although this is not required.

These are automated machines and may move unexpectedly. Keep your body parts out of pinch points, especially behind the table and between the table and cutter.

The tools themselves are very sharp and should be given the same respect that you would give a scalpel or sharp knife.

Preparing Parts for the CNC Mills

The first thing after designing your part in a 3-D modeling package like Mechanical Desktop (Matt's Choice) or Pro-Engineer (Dan Boy's Choice) is to get the part ready to be machined. You need to hold the part in the mill's vise and yet allow the tool to cut around the entire part. This is best accomplished by mounting the part in a frame with sprues to connect the part to a frame. You should end up with a finished part that is held in a frame like plastic model airplane parts come in the box. See the example pictures included.



Note: Tip when mounting part in frame:

1. The sprues should be taller than they are wide, but not the full thickness of the part.
2. The part should have 1.5 times the cutter diameter space between the part and frame.
3. You should have at least one sprue per side.
4. The frame should be a nominal thickness that is the same as your stock (i.e 1/8 inch 1/4 inch, 3/8 inch.)
5. The frame should also be relatively thin. You don't want to spend too much time to machining the frame. 0.01 inches is a pretty good frame thickness.

Once the part is laid out in its frame the part needs to be exported in STL format for transferred to the computer that is connected to the CNC Mills.

Exporting Mechanical Desktop parts as STL files

With Mechanical Desktop you will need to make a copy of your part. Make sure the part is in the positive octant (all coordinates of the entire part must be positive.). Then use the <explode> command to explode the part changing from a mechanical desktop part into a true 3-D solid. Set the system variable { facetres } to between 2-4. This affects the density of the STL-mesh. Switch to the world coordinates and orient the part so that the tool's rotation is about the z axis. Once oriented correctly use the <stlout> command. Chose the solid, say NO to the "create binary file?" and give the file a name.

Note: If you have more curves, set the {facetres} parameter higher. If you have a part with very large or no curves you can leave this number smaller and the STL file will be much smaller.


If you only need to machine from one side to capture the desired features then you are done. If you need to machine from both sides then you will need to rotate the part 90 degrees positive about the world Z axis and output a second STL file. A good naming scheme here is to give the first side a *filenameA.stl* and then *filenameB.stl*. Once these files are created send them to the computer connected to the CNC mills.

Exporting ProE drawings as STL files

1. Before beginning the drawing, create datum planes for the part. You can do this on the window by: *Feature>Create>Datum>Plane>Default*. This should be done before starting any drawing.
2. When the drawing is complete, use *File>Export>Model>STL* to create the STL file.
3. In the format window that pops up, be sure to select ASCII.
4. Adjust the chord length to produce a fairly smooth shape; smaller chords produce smoother shapes and bigger files.
5. Click Apply to see if the surface looks acceptable.
6. Click OK to export the file. It will default to the Bin directory.

This process will work for assembly files as well as parts. It is suggested that you design the part(s) and sprue as separate parts, assemble them, and convert the assembly to a STL file.

Loading Material into the CNC Mills



PNC-2500 the small CNC mill

Before setting up the computer attached to the CNC mills you will need to load the mill with a blank piece of material. This blank should be at least 1/2 inch bigger on each side then the frame around your part. This will leave a 1/4 inch extra material around your entire part. This should be stiff enough in most cases to keep the frame flat when you machine the second side. The blank should also be the same thickness as the frame in the drawn part.

Note: If the blank is slightly thicker then the actual nominal dimension this can be adjusted for before the part is machined. Measure the blank before loading and remember the difference between the measure blank thickness and the nominal frame thickness.



PNC-3100 Larger CNC Mill

Now load the blank in the machine. Turn the mill on with the large square yellow button on the front of the mill controller. Allow the machine to run its self-check and calibration after the table has finished moving you can put the blank in the vise of the mill. On the larger machine, the PNC-3100 be sure to use the parallel blocks to put the part as near top of the vise as possible. In either case you need to be sure that the blank is pressed firmly down into to the vise to ensure that the part is flat. For the setup process you will need put a 1/8-inch mill in the collet.

Note: The collet on the PNC 3100 requires only one wrench to hold the spindle and is then tightened by hand. The PNC 2500 used two wrenches-one on the spindle and one on the collet. Be sure the collet is tight but do not over tighten. You should not have to herniate yourself doing this. Be sure that the spindle switch on the front of the machine is off when loading a tool. This ensures that the spindle cannot turn on.

Uses the pendant to move the tool to the lower left corner of the blank. Use the X and Y button on the pendant for coarse movement and then the jog button and jog wheel to make fine movements. To use the jog wheel select the axis you want to move with the jog button and then turn the wheel the appropriate direction. Using a ruler move the tool 3/16 in from both left and front edge of the blank. This gives the 1/4 inch to the center of the tool. Place the end of the ruler against the tool so that the entire end of the ruler is in contact with both flutes and tool shaft. Then you can measure 3/16-inch on the edge of the blank. Once you have the tool 3/16 from both the left and front side you will need to set this as (0,0,0) in the machine coordinates. To do this, hold down the [Enter] button and then press [Home] button releasing them together. The X and Y values of the pendent should go to zero. Will get to the Z-axis shortly.



Pendant for CNC mill

Note: The PNC 3100 will remember this setting if you have to cycle the power-the PNC 2500 will not.

Next you will need to mark this point on the blank for later reference when aligning the part for machining the other side. To do this make sure the blank and cutter is clear of rulers, finger, and any other foreign object you do not want a hole in and drill a 1/8-inch hole through the part with the 1/8 inch end mill. To do this, turn the spindle on by holding the spindle test [ON/OFF] button until the spindle starts.



Spindle Switches: PNC 2500 top, PNC 3100 bottom

Note: If the spindle does not turn on make sure the spindle switch on the front of the mill head is in the on position. You hopefully had turned this off when you put the tool in the spindle. The knob on the front of the controller box is the manual spindle speed control. Be sure spin the tool fast enough for the material you are cutting. For most materials as fast a possible will work fine, but some materials will melt onto the tool and brake it. Plexiglass is a prime example of a material that must be machined slowly with a lower RPM cutter.


Now that the spindle is running press the [JOG] button until the Z-axis LED is light up. Double check that you are still at X = 0 and Y = 0. Use the JOG knob to slowly lower the head of the mill to drilling a hole through the blank. Make sure that the blocks are moved so you do not hit them when drilling through. Do not to drill into the vise below. Once drilled through the blank withdraw the tool and turn the spindle off by pressing the spindle test [ON/OFF] button.

Next choose the tool that will be used to cut the part. Remember the larger the tool the fast the part will machine. The smaller the tool the finer detail that you will be able to capture. Put the chosen tool in the mill, move over to the left about 1/8 (about 300-400 units on the pendant) and do "touch test" with a spinning tool to find the top of the blank. To do this start the spindle with the spindle test [ON/OFF] and use the Z JOG to move down very slowly until you just see the first very small chips come off the blank. You will have to look very carefully to see this (extra light here helps). Be sure you are wearing you safety glasses. You should be able to hold 0 to -0.002 thousands accuracy with only a little practice. Once you have the tool at the surface of the blank set this as Z-Zero by pressing and holding [Enter] and then press [Z0] and release both.

If you mess up just move to a different part of the blank out on the frame and try again. You have now set up the CNC machine for machining.

Note: The units displayed on the pendant are hundredths of a millimeter.


Setup Computer to Send Tool Paths to CNC Mill



Now you will need to run the software to actually communicate with the CNC mills. The program is Modela 3D Player. It should be in *Start->Programs->Modela Apps group->mdx3p*. This program will take your STL file and calculate the need tool paths to cut your part.

After running the app use the *file->open* command and open the *filename.A.stl* file. This should open and display you STL part file.

First select the CNC milling machine that you have just set up in the previous section. This is in the *File->Print Setup* dialog box. Your choices should be Roland CAMM-3 PNC-2700(this is the driver for the PNC-2500), Roland CAMM-3 PNC-3100 and maybe one or two actual printers. Be sure not to pick a printer but pick the machine that holds your part blank. Press *OK*.



Next go to *Option->Layout* dialog box. Set the LowerLeft X, LowerLeft Y and Margin to Zero. This will move the point (0,0,0) to the point you setup on the mill. By setting the margin to zero the cutter will not be allowed to leave the box defined by the frame around your part thus keeping the frame attached to excess material on the blank. Click *OK*.

Be sure that there is not a check next to *Abstract* on the *Option->Abstract* menu. If there is, simply click on *Option->Abstract* to remove it.




On the *Option->Path Direction* dialog box and set draft to *Contouring*. If you do not expect to need fine passes then be sure to check the *Contoured* check box. This will make the cutter cut an exact perimeter around you part after each material removal pass. If you are going to do fine passes then you do not need to waste time doing this. The roughness left by the material removal passes will be cleaned up in the fine passes. On the fine side of the dialog box choose X Scan Line, Y Scan Line, or X + Y Scan Line passes depending on you needs. Click *OK*


Note: For fine pass directions use fine passes the are perpendicular to the axis of the prominent curves that are present in the part. High precision should only be used for very small parts. This will not slow down actual machining time but will greatly increase the time to calculate the tool paths.

Now you will need to use the [NEXT] button at the bottom of the screed to step through next several screens.

Click [NEXT] once and you will come to the direction screen. Chose what orientation you would like to machine from. In most cases you should machine *filename* A.stl from the top and *filename* B.stl from the bottom.



Click [NEXT] once and you will be at the Size screen. Pick a known dimension of one side of the part and enter this into the appropriate field by clicking on the field. It will scale the other dimensions correctly.




Click [NEXT] once and you will be at the depth screen. On this screen set the maximum depth the tool will be allowed to cut. Note: don't cut deeper then needed to capture the detail this will only waste time. Also make sure not to hit the shaft of the tool on the frame or part.



Note: In general these are safe max depth settings
 1/32 inch end mill will cut 0.1 inch deep
 1/16 inch end mill will cut 0.2 inch deep
 3/32 inch end mill will cut 0.25 inch deep
 1/8 inch end mill will cut 0.5 inch deep


Click [NEXT] once and you will be at the tool page. Click the tool diameter field and enter the diameter of the tool. You can enter either decimal or fraction dimensions. Then choose whether you are using square end or ball-end end-mill. Here you will also choose Draft or Fine passes. Be sure to do Draft passes before Fine passes. Select an appropriate material from the list of materials.




Note: If you need you can create your own material in the option menu. You will need to know the appropriate tool feed speeds for the material and tool diameter.

Note: For most things a square-end mill works great. If most of the surface are flat then this is the best choice. If you have many concave surface features then a ball-end mill would be the better choice to achieve good surface finish.

Click [NEXT] once and you will be at the review screen where you started. At this point you NEED TO DOUBLE-CHECK ALL SETTINGS. When you are happy with the setting click the [Tool Path] button and it will calculate the tool paths and display them on your part. Inspect this carefully and make sure it is capturing all the details you expected.





If you need to compensate for a material blank that is slightly thicker than the nominal dimension, now is the time to do this. Go to the Options->Layout dialog box and in the lower left corner enter the difference between the frame thickness and the actual thickness of the blank in thousands of an inch in the surfacing depth box. Leave the automatic box checked and when the mill is clear of all furry defenseless critters click the [START] button that in in the dialog box not the one at the bottom of the screen. The machine will remove the excess thickness and reset your Z-zero. Click OK and continue on.

Make sure you and your friends (the ones you still like) are clear of the machine and click the [START] button.

The program will download the data to the CNC controller. The Mill head should rise to the top of its stroke shortly after sending the data, and then 20-30 seconds later the spindle should start and begin cutting. If you are using the PNC 2500 then be sure that the spindle speed is set manually on the front of the controller. The PNC 3100 spindle speed should be set already in the software. Be sure to stay with the machine while it completes its first two passes. Watch to make sure it will not hit the vise and that it is doing what you expected. On the second pass watch the depth to make sure this is not too deep for the material you are cutting. If the machine is laboring shut it off and choose more conservative parameters and try again. If at anytime you fear for the machine's or your own safety punch the [ON/OFF] button. This will shut down the machine and save you and the machine from injury, but you will have to re-setup the mill to try again.

Once the draft passes are sent to the mill you can send the fine passes. Click on the [Draft] button and this will take you to the tool screen where you can select [Fine]. Use the [Back] button and you will come back to the review screen. Click on [Tool Path] button, inspect and then press [Start]. You can send both the draft and fine passes immediately to the CNC controller the computer will buffer as needed. You can also then send data to the other machine by selecting that machine in the printer setup dialog box.

The second side

To machine the other side you will need to flip the part over in the vise so that the reference hole drilled earlier is still in the lower left corner. Put a tool in backwards so that square smooth end of the mill is sticking out of the spindle. Put the part on the tool shaft and use the pendant to VERY CAREFULLY lower the part into the vice. Move the part down onto the blocks and center against the stationary jaw of the vise. This is somewhat difficult to do and will take practice. Be careful and do most of your movement with the JOG wheel not the direction button on the pendant. Once you are against the stationary jaw of the vise tighten the vise down on the partial part. Zero the X and Y Coordinates by holding [Enter] then press [Home] release both. This is a good approximate Zero. The X direction will be dead on but the Y direction could be off by a little bit due to over or under loading the blank as you move against the stationary jaw of the vise. Use the Y JOG wheel and the Z up and down buttons to move the tool in and out of the hole adjusting the Y coordinate until the tool goes cleanly and easily in and out of the hole with no perceivable flexion of the tool. This should put you within +/- 0.003 inch of the hole's center. Re-Zero your X and Y coordinate by holding [Enter] then press [Home] release both. Put your tool of choice in the machine and do a Z surface find as done earlier. The machine is now ready for the second side.

The computer setup is pretty much the same except load the *filenameB.stl* file and be sure to select machine from bottom on the direction page. Everything else should be the same.