




How to Make a Lofted Surface with a Smooth Tip



This demonstration shows:

- ▶ How to create a tubular lofted surface end with a smooth tip.

You must know:

- ▶ Curve drawing (**Curve**)
- ▶ Lofting (**Loft**)
- ▶ Turn control points of a surface on (**PointsOn**) and off (**PointsOff**)
- ▶ Object snaps
- ▶ Move objects (**Move**)



To create a lofted surface with a smooth tip:

The completed model with steps is [loft01.3dm](#).

- 1 In the **Front** view, use the **Curve** command to create several closed curves.

Note: If you want the tip to be perfectly round, make sure the cross section curve next to the tip is planar and convex. (If you stretch a rubber band around the control points of a convex curve, the band will touch all control points).

- 2 Drag the curves in place in the **Perspective** view.







- 3 Use the **Loft** command with **Point** option to create a surface.

Pick a starting point in front of the curves and then pick the rest of the curves.

This loft will have a sharp tip.




- 4 Use **PointsOn** to turn on the control points of the lofted surface.




- 5 **Zoom** in on the tip of the loft.


There is a ring of control points near the tip.



- 6 Draw a **Line** between control points on the opposite sides of the loft using **Point** object snap.



- 7 Select the control point at the tip of the loft.





- 8 Use **Move** combined with **Point** and **Mid** object snaps to move the control point from the tip to the middle of the line.

