

FIRMWARE RECORD for CJ-70/60

RFW-005

1

4.30 --- Latest version as of today.

[bug fix]

1. The problem that the SUM ERROR REWRITE MEMORY happens when it is powered on because the bit of a specific address in the FLASH memory changes to 0 from 1 has been fixed.

[Serial No.]

CJ-70 :

Z**1765 and above

CJ-60 :

Z**0400 and above