

**Roland Troubleshooting Tips** Topic: PC-600 - What to do if...

ST083104

## What to Do If...

## **Cartridge detection is incorrect**

Has a marker seal on a ribbon cartridge become dirty? Wipe off any grime on marker seals.

Are ribbon cartridges designed exclusively for the PC-600 being used? Use only exclusive PC-600 ribbon cartridges.